
PRESSURE TRANSDUCERS RECOMMENDED EXTERNAL CIRCUIT

■ RECOMMENDED EXTERNAL CIRCUIT

ullet 1 \sim 5 V Output



lepha In case of being required the improvement of accuracy, high accuracy amp. such as LT1014 is recommended

lacksquare 0 \sim 1 V Output

