

# HANDLING NOTES

## BRUSHLESS DC FANS

- When mounting Brushless DC fans, tighten the screw at torque levels less than those shown below for the breakage and transformation prevention.

F16EA: 80 mN·m maximum

F17FA: 80 mN·m maximum

F17HA: 80 mN·m maximum

F251R: 400 mN·m maximum

F310R: 400 mN·m maximum

F412R, F410T: 588.4 mN·m maximum

F614T: 784.6 mN·m maximum

- Do not attempt to modify or disassemble the Brushless DC fans.
- Do not hold or carry Brushless DC fans by the lead wires.
- Please avoid mechanical shock because of precision bearings structure.